



ERRATA CORRIGE

We inform you that at page 132 of the Product Catalogue 2022 the dimensions of P/N 1608380, 1608381, 1608384 and 1608510 and the wire section of P/N 1704000 are wrong.


Please find the correct information highlighted here below.




1




2




3



4



5



6

IMG	DESCRIPTION	L mm	L1 mm	L2 mm	SCREW	WIRE SECTION mm ²	MATERIAL	MATERIAL THICKNESS mm	P/N BOX	MOQ
1	FDU G90	23	16,7	17	M8	25÷40	CuZn-Sn	1,5	1608380	1500
	FDU G90	23	16,7	17	M6	25÷40	CuZn-Sn	1,5	1608381	700
	FDU G90	27,4	12,6	17	M6	25÷35	Cu-Sn	1,5	1608384	600
	G90	23	16	16	M8	40, 50, 70	Cu-Sn	1,8	1607500	600
	G90	24	16	16	M8	30 + 30	Cu-Sn	1,8	1617500	600
2	FDU G90				M6	25÷40	CuZn-Sn	1,5	1608382	700
3	PTC G90	17,6	15,4	14	M8	2,5÷4	Cu-Sn	0,8	1608500	1700
	STR-S G90	17,3	11,4	12,7	M6	2,5÷4	Cu-Sn	0,8	1608510	2300
4	FDU GM90M6P				M6	25÷35	CuZn-Sn	1,5	1704010	600
5	SX FL90 P				M6	25 - 35	CuZn-Sn	1,8	1704000	500
6	NEGATIVE BATTERY RING TERMINAL				M6	35 - 50	Cu-Sn	1,5	1600047	500

The catalogue on the MTA website is already updated.